



Report Summary

Client:	John and Kathy Sandmann
Address:	58180 Indian Lake Rd Dowagiac, MI 49047-9331
Contact:	(269) 687-8160
Septic:	Satisfactory
	Deficiencies and Malfunctions: NONE

Richmond Sanitary Service

12516 Hoffman Rd

Marcellus, MI 49067

269 646 5368


Septic Report

Client:	John and Kathy Sandmann	Evaluation #:	58180
Address:	58180 Indian Lake Rd Dowagiac, MI 49047-9331		
County:	Cass	Township:	Pokagon
Occupied:	YES		
Pumper:	Richmond Sanitary	Date Pumped:	9/27/24
Septic Tank Location:	South of House	Final Disposal Location:	South of House
Septic Tank Capacity (Gal):	2 - 750 gallons, 1500	Baffled:	Yes - Pipe
Final Disposal Type:	Drain field	Effluent Filter:	No
Septic Tank Malfunction:	NONE	Final Disposal Malfunction:	None
Injection Pump:	No	Injection Pump Condition:	
Dosing Pump:	No	Dosing Pump Condition:	
Notes and Observations: Septic system appeared to be in working order at time of inspection.			
Evaluated By:	Sarah Huff		
Approved By:		Date:	10/1/24

This report should not be construed as a guarantee of future functionality nor deemed as a warranty against failure due to the multitude of factors that contribute to the success or failure of a septic system.

Measurements

Drawing not to scale.



Septic- Final Disposal (Ft)	10'	Septic- House (Ft)	11'
Septic- Property Lines (Ft)	>10'	Septic – Well (Ft)	>90'

Evaluated By:	Sarah Huff	Locator Used:	
Approved By:	<i>Sarah Huff</i>	Date:	10/1/24

